

## BUILDING SAFETY CERTIFICATE

To be filled by the Inspecting Officer (Subdivisional Engineer)  
(Re:G.O.Ms.20/70/PWD Dt. 13-01-1970)

1. Name of the Officer :- Sub Divisional Engineer, P.W. Sub Division No. 4, Nagpur
2. Name of the School :- Adarsh Sanskar Vidyalaya CBSE
3. Location with name of Education District Sub District :- Khasra No. 200/2, Pipla, Hudkeshwar Road, Dist. Nagpur
4. Classification of Building as specified in Column 4 of the application for fitness :- **R.C.C. Frame Structure**

Certificate and size

	Wing A	Wing B	Year
G.F.	3.70 Mt. Height	3.70 Mt. Height	(2023-24)
F.F.	3.70 Mt. Height	3.70 Mt. Height	(2023-24)
S.F.	3.70 Mt. Height		(2023-24)

5. Period for which the certificate is issued :- 2024-25
6. Nature of defect, if any
- |                                 |    |                        |
|---------------------------------|----|------------------------|
| a) Foundation and basement      | :- | } No Any defects Occur |
| b) Superstructure               | :- |                        |
| c) Door and Windows             | :- |                        |
| d) Wood work wrought and put up | :- |                        |
| e) Roof                         | :- |                        |
| f) Flooring                     | :- |                        |
| g) Miscellaneous                | :- |                        |
7. Any major defects noticed which will render The building unsafe in any manner :- No
8. Whether maintenance work have been done Properly :- Seen
9. Whether the structure is sound or not Conducting classes :- **Structure is in Good Condition**
- Note :- 1. The stability of the structure should be examined also with reference to location, altitude, Intensity of Wind, Exposure of flood etc.  
2. Any additional observation if deemed necessary for the certificate may be furnished Separately with this certificate

O.W.No. 05/4/Tech/2024-25

Date – 06/05/2024

### CERTIFICATE


**Certified that the Structure of School Building was Inspected by me on Dt. 02/05/2024 and found to be fit/unsit to conduct classes for the period 2024-25. For the reason stated above. Necessary Certificate regarding Electrification Fitness and Fire Fighting provision as per Building Code should be obtained by owner of Building.**

Place :- Nagpur  
Date :- 06/05/2024

  
Sub Divisional Engineer  
P.W. Sub Division No. 4  
Nagpur

Counter Signature  
  
Executive Engineer  
P.W. Division No. 1  
Nagpur

  
Manager  
Adarsh Sanskar Vidyalaya (CBSE)  
Pipla, Hudkeshwar Road, Nagpur.

  
Principal  
Adarsh Sanskar Vidyalaya  
Pipla, Nagpur-34  
AFFILIATION NO. 113045